INTOX EC/IR II

Quality Assurance Worksheet

Instrument	Serial Number	010615	Worksheet Start Date	10/8/201	3.	
Location	;	DFS-Gentral	Whitese			
Address						
DFS Technician		Michelle Billeter	License	License No.		
				☐ On-Site		
	1	Site Specifications		Yes	No	
	Secured Environment Location must not be a	:: ccessible to the general public.		Γ	Г	
2	Environment free fror	n contaminants		Г	T	
	Dedicated telephone I The phone line should	line: be used solely by the instrument	,	J	 	
	Adequate Ventilation: Enough space must be to allow for adequate ve	provided for the instrument and	the printer	Γ	Γ	
	Stable temperature co The instrument should temperature variation.	ontrols: not be exposed to direct sources	s of	г	Γ	
		e: trument power circuit should not machines or other high amperag		٣	Γ	
	Room Condition: The site should be free	of excessive moisture, heat and	dust.	Γ	厂	
E-Seek Keyboard Printer UPS	Old serial no. ι	New serial no	Mouthr Certific			
Maintenand	and the control of t	the calien.				
Comments	(if any)					

Intox EC/IR II QA Worksheet Issued by Calibration and Training Program Manager Issue Date: 4-March-2013 DFS Document 250-F113 Revision 6 Page 1 of 2

Instrument Serial Number	010615		Certification Da	ate		
Instrument Barometer (mm HG) 761			Reference Barometer (mm		HG)	762
Reference Barometer(RB)Serial #	009111		RB Calibration	Due	5/23/2014	
Standard (sea level) 0.25 Precision 0		minimum 0.000 sample min 0.000	maximum 0.000 sample max 0.000		Sample 1 Sample 2 Sample 3	
Standard (sea level) 0.15 Precision 0		minimum 0.000 sample min 0.000	maximum 0.000 sample max 0.000		Sample 1 Sample 2 Sample 3	
Standard (sea level) 0.08 Precision 0		minimum -0.003 sample min 0.000	maximum 0.003 sample max 0.000		Sample 1 Sample 2 Sample 3	
Standard (sea level) 0.02 Precision 0		minimum -0.003 sample min 0.000	maximum 0.003 sample max 0.000		Sample 1 Sample 2 Sample 3	
(네너스 all measurements are Estimation of Uncertainty of Meas	•	ability records a	are located with	in the Breath	Alcohol Section	ı
Calibrated	Certified	·	Г Replaced di	y gas standa	ard (+O-ring)	
Dry gas standard Lot i	No. (with tank no.)					
Measurement Assurance Che				(Instrument a	Test) y condition of the	e item)
Standard (sea level)		minimum	maximum		Sample 1	
0.10 Precision ' 0		-0.003 sample min 0.000	0.003 sample max 0.000		Sample 2 Sample 3	
DFS Technician	Midule	Bil	de	Date	6/3/14	
رے Issuing Analyst	Mulelle	Belli	<u> </u>	Date	6 B 14	
Intox EC/IR II OA Worksheet				DE	S Document 256	1_F113

Intox EC/IR II QA Worksheet
Issued by Calibration and Training Program Manager
Issue Date: 4-March-2013

Revision 6 Page 2 of 2

6/2/14

Intox EC/IR II: Calibration

Department of Forensic Scip

- Test Mumber: 300 Scrial Member: 714615 Test Time: 11:50 EPT t: 0.100 Exp Date: 10/17/2013 Test Date: 10/08/2013

Dry Gas Target:

Lot Number: AG129094-13

Baron/bric Pressure: 702 mally Tank Pressure: 149 psi

System Check / Fassed

BLK

Test/Status: Success

CalZbration CRC: E2270010

Performed Calibration instead of one point certification prior to firmuse Software upgrade.

10/8/13 mmB

/TLN 6/2/14

Intox EC/IR-II: Certification

Department of Forensic Science Serial Number: 010615 Test Sumber: 001 Test Date: 10/08/2013 Test Time: 12:42 EDT

> Technician Initia/s: MNE System Check: Fassed

Test	g/210L	Time				
DIAG	F://a = =	4	<u>.</u>	2	e j	Ĩ.
24.4 (42)	A dika		7		.1	٧.

Ambient/RFI Detected

Standard Value (at sea level): 0.000 3.000

Certification Status: Failure